ian eta i eta i

		·		25X1
VALUATION	PLACE ORTA	NED		25X1 <b>-</b>
ATE OF CONTENT.	<u> </u>	TE PREPARED	2 June 19	525 <b>X</b> 1
	OSURES (NO. & TYPE)		legend on ditte	25X1
EMARKS				25X1
	This is UNEV		25)	X1 <del></del>

- There were no terrain obstacles in the immediate vicinity of Drewitz airlield. The subsoid of the field consisted of sand, and the ground water level was at a depth of about 30 meters. Coniferous woods surrounded the installation. The nearest railroad station was Jaenschwalde. The field had rail and road connections. Construction of the airfield was begun in February 1951. The runway was completed in April 1954. New buildings and housing facilities were continuously being erected.
- The runway of the field was about 2,500 meters long, 80 meters wide, and had a concrete layer 30 centimeters thicks Portland cement and basalt chippings had been used in the construction of the runway. Concrete aircraft revetuents measuring 10 x 30 x 4 meters, extending 3 meters below ground and projecting about 1 meter above surface were available on both sides of the runway. The revetuents were covered with brown terpaulins, and texiways extend to each of them. The ground surface of the revetments was covered with metal sheets. Two rows of 150 lamps each were on each side of the runway, while the runway ends were lighted by one row of 8 lamps each. The lamps were centrally controlled from the flight control station and were 50 centimeters above ground. The field was level and had a grass cover
- 3. The fuel dump of the installation was in a pit of 100 x 30 meters and was 10 meters deep, Walls, floor and ceiling of the dump consisted of concrete 50 centimeters thick. Aircraft refuelled from fuel trucks outside of the aircraft revetments.
- The field was surrounded by a barbed wire fence two meters high, Three permanently eccupied guard stations were available. The fence was patrolled.

Comment. Drewitz airfield is still believed to be eccupied by Aereclub

700 and Technical Base 302. The report partly agrees with previous information.

The location of the spur truck as indicated in the attached sketch requires confirmation. The existence of semi-underground aircraft revetments has been reported for the first time. For layout of the installation, see Annex.

7 lust

25**X**1

CLASSIFICATION CONFIDENCE AT

25X1